

10.0 REFERENCES

ABB Environmental Services, Inc., 1992. Final Report: Air Sampling for Chemical Analysis from Rocket Engine Test Firing Plumes at the Rocketdyne Santa Susana Field Laboratory. Submitted to Rocketdyne Division, Rockwell International, Corporation, Canoga Park CA, June 12, 1992.

AEHS, 2003. Study of State Soil Arsenic Regulations.
<http://www.aehs.com/publications/catalog/contents/arsenic.pdf>. Amherst, MA. Pub. # 01002.

Allwest Remediation, Inc., 2005. Phase II Site Investigation Report on Findings: Centex Homes—Sterling, West Hills, CA. Prepared for Morrison and Foerster LLP by Allwest Remediation, Inc., Anaheim, CA. July 26, 2005.

Andelman, J.B., 1985. Inhalation Exposure in the Home to Volatile Organic Contaminants of Drinking Water. *Sci. Total Environ.* 47: 443-460.

Anttila, A., E. Pukkala, M. Sallmen, S. Hberg, and K. Hemminki. 1995. Cancer Incidence Among Finnish Workers Exposed to Halogenated Hydrocarbons. *JOEM.* 37: 797-804.

ARB. 1998. Proposed Identification of Diesel Exhaust as a Toxic Air Contaminant. Part A, Exposure Assessment. California Environmental Protection Agency, Air Resources Board.

Atomics International, 1960. Unpublished memo #5427 Re. Env. Monitoring Annual Report for 1959, June 24, 1960.

Atomics International, 1962. Evaluation of the Atomics International Nuclear Development Field Laboratory as a Location for Reactor Facilities. R.L. Ashley, Ed. NAA-SR-7300. May 25, 1962.

ATSDR, 1990. Toxicological Profiles. Agency for Toxic Substances and Disease Registry, 1990.

ATSDR, 1993. Toxicological Profile for *n*-Nitrosodiphenylamine. Atlanta, GA: U.S. Department of Health and Human Services, Public Health Service.

ATSDR, 1997a. Toxicological Profile for Hydrazines. Agency for Toxic Substances and Disease Registry, Atlanta GA, September 1997.

ATSDR, 1997b. Toxicological Profile for Polychlorinated Biphenyls (Update). Agency for Toxic Substances and Disease Registry, Atlanta GA, September 1997.

ATSDR, 1998. Toxicological Profile for Chlorinated Dibenzo-p-Dioxins (Update). Agency for Toxic Substances and Disease Registry, Atlanta GA, December, 1998.

ATSDR, 1999. Public Health Assessment: Draft Preliminary Site Evaluation of Santa Susana Field Laboratory (SSFL), Ventura County, California. Prepared by the Division of Health Assessment and Consultation, Atlanta, Georgia. CERCLIS NO. CAD074103771. December 3. <http://www.atsdr.cdc.gov/HAC/PHA/santa/santasus.htm>.

ATSDR, 2000. Draft for SSFL Site Evaluation. Agency for Toxic Substances and Disease Registry, Dec 3, 1999, (Cerclis #CAD074103771).

- ATSDR, 2002. Toxicological Profile for Trichloroethene (Update). Agency for Toxic Substances and Disease Registry, Atlanta, GA, December 2002.
- Axelsson, O., A. Selden, K. Anderssen, and C. Hogstedt, 1994. Updated and Expanded Swedish Cohort Study on Trichloroethylene and Cancer Risk. *J. Occup. Med.* 36: 556-562.
- Ball, W.P., and P.V. Roberts, 1991. Long-Term Sorption of Halogenated Organic Chemicals by Aquifer Materials—Part 1. Equilibrium. *Environ. Sci. Technol.* 25(7): 1223-1236.
- Bechtel Jacobs Company LLC, 1998. Department of Energy-Oak Ridge Operations Environmental Management Program Risk Ranking Methodology. (DRAFT) BJC/OR-127. Bechtel Jacobs Company, LLC, Oak Ridge, TN.
- Blackshaw, G.L., 1959. Release of Fission Gases from the AE-6 Reactor on March 25, 1959. Atomic International NAA-SR-Memo #3757, April 15, 1959.
- Boeing, 1990-2003. National Pollutant Discharge Elimination System (NPDES) Permit for the Boeing Company, SSFL. Electronic Sample Data Set. Annual Reports, Permit # CA0001309.
- Boeing, 2002. Perchlorate in NPDES Surface Water Samples, Boeing-SSFL Perchlorate Data Summary for NPDES Outfalls 001-007 and Happy Valley, Jan '98-Dec-02.
- CA EPA, 2000. Letter of Bell Canyon Residence (Sample 971060) Area Evaluation of Split Sample Results, from T.R. Hathaway, CALEPA, to Penny Nakashima, DTSC, PCA Code 24120.
- Carey, S.M., 1981. Sandstone Petrography of the Upper Cretaceous Chatsworth Formation, Simi Hills, California. In Link, M.H., Squires, R.L., and Colburn, I.P., eds., 1981. *Simi Hills Cretaceous Turbidites, Southern California. Soc. Econ. Paleontol. Mineral., Pacific Section.*
- Carter, W.P.L., E.C. Tuazon, A.M. Winer, and J.N. Pitts, 1981. Gas Phase reactions of N,N-Dimethylhydrazine with Ozone and NO_x in Simulated Atmospheres: Facile Formation of N-Nitrosodimethylamine. In: Scanlan, R.A., and S.R. Tannenbaum, eds., 1981. *N-Nitroso Compounds.* Washington, DC: American Chemical Society. pp. 117-131.
- Carter, W.P.L., D. Luo, and I.L. Malina, 1997. Investigation of the Atmospheric Reactions of Chloropicrin. *Atmos. Environ.* 31: 1425-1439.
- CDHS, 1990. Cancer Incidence Rates in Five Los Angeles County Census Tracts. California Department of Health Services, Oakland, CA.
- CDHS, 1992. Cancer Incidence near SSFL Laboratory, 1978-1989. California Department of Health Services, Oakland, CA.
- CDHS, 1999. Overview of California's Perchlorate Experience. http://www.dhs.cahwnet.gov/org/ps/ddwem/chemicals/perch/perchl_overview.html. Last update September 23, 1999.
- CEPA (Canadian EPA), 1993. Priority Substances List Assessment Report: Trichloroethylene. Canadian Environmental Protection Act. Environment Canada, Health Canada.

CH2M Hill, 1993. Records Search and Trichloroethylene Release Assessment for the Santa Susana Field Laboratory, Ventura County, California. Prepared for the National Aeronautics and Space Administration, Doc No. MGM33496.Q0, June, 1993.

Chinkin, L.R., and Ryan P.A., 2004. Assessment of Off-Site Exposures and Potential Health Implications from the Santa Susana Field Laboratory (SSFL): Toxic Organic and Heavy Metal Emissions from SSFL Operations, 1948 to Present. Draft final report prepared for the Center for Environmental Risk Reduction, University of California, Los Angeles, CA, by Sonoma Technology, Inc., Petaluma, CA, STI-900920-2482-DFR, February.

Cohen, Y., A. Winer, R. Turco, and M. Suffet, 2000. Air Toxics. Institute of the Environment Southern California Report Card 2000.

Colburn, I., L.R. Saul, and A.A. Almgren, 1981. The Chatsworth Formation: A New Formation for the Upper Cretaceous Strata of the Simi Hills, California. In Link, M.H., R.L. Squires, and I.P. Colburn, eds., 1981. Simi Hills Cretaceous Turbidites, Southern California, Pacific Section. Society of Economic Paleontologists and Mineralogists.

Committee to Bridge the Gap, undated. List of Accidents and Incidents at SSFL. Unpublished document, Committee to Bridge the Gap, Los Angeles, CA.

Costa, J., 2003. AB 2588 Air Toxics “Hot Spots” Emission Inventory Report for Areas I, II, and III. Facility Year 2002. Facility #00232. The Boeing Company. Environmental Protection Manager.

Cotton, F.A., and G. Wilkinson, 1982. Advanced Inorganic Chemistry. 3rd ed., John Wiley and Sons, NY.

Crank, J., 1975. Mathematics of diffusion. 2nd edition, Clarendon Press, Oxford.

Cussler, E.L. 1997. Diffusion Mass Transfer in Fluid Systems, 2nd Edition. Cambridge University Press.

Dempsey, G., 1990. Unpublished letter on sample results from around SSFL, from G. Dempsey, EPA Radiation and Indoor Environments Laboratory, Las Vegas NV, to B. Watson, DHS-EMB, January 12, 1990.

Dempsey, G., 1997. Unpublished memorandum on Area IV Radiological Characterization Survey, from G. Dempsey, EPA Radiation and Indoor Environments Laboratory, Las Vegas NV, to T. Kelly, EPA Region 9, San Francisco, CA, 1997.

DeRosa, C., D. Brown, R. Dhara, et al., 1997. Dioxin and Dioxin-Like Compounds in Soil, Part I: ATSDR Interim Policy Guideline, Toxicol. Indust. Health 13(6): 759-804.

DHHS, 1994. National Toxicology Program. Seventh Annual Report on Carcinogenesis. Prepared for the National Institute of Environmental Health Sciences by Technical Resources, Inc., Rockville, MD.

DHS, 1988a. DHS Inspection Report, Notice of Deficiency, Rocketdyne International, Jan 5, 1988. California Department of Health Services, 0005781988, June 29, 1988.

DHS, 1988b. Proposed Maximum Contaminant Level for 1,1-Dichloroethane. California Department of Health Services, Health and Welfare Agency, Sacramento, CA.

DHS, 1989a. Unpublished letter re: Inspection Report for inspections dated June 19, 20, 28, 1989, from DHS (Vajie Motiaford) to Rocketdyne (7129189-CAP093365435).

DHS, 1989b. Unpublished letter re: Nov. 1989 Addendum Report, RD Corp SSFL, Area IV, EPA ID #CAD000629972 and CA389009000. DHS (Scott Simpson) to Rocketdyne (Steve Lafflam), August 11, 1989.

DHS, 1991. Unpublished letter concerning May 28, 1991, inspection. DHS (Vajie Motiaford) to Rocketdyne, June 14, 1991.

DHS, 1992. Cancer Incidence Near the Santa Susana Field Laboratory: 1978-1989. Prepared by M. Coye and L. Goldman of the California Department of Health Services, March 27, 1992.

DHS, 1999. Unpublished letter re: sub comments on Draft Closure Plan Haz Waste Man Fac Area IV, EPA ID#CAD000629972. DHS (G. Sweel) to SSFL (P. Chandler), SSFL, May 13, 1999.

DHS, 2001. Drinking Water Standards, Primary Maximum Contaminant Levels (MCLs) and Lead and Copper Action Levels. California Department of Health Services, Health and Welfare Agency, Sacramento, CA.

DOE, 1989. Environmental Survey Preliminary Report, DOE Activities at SSFL, Ventura Co., CA. U.S. Department of Energy, Office of Environmental Audit, February 1989.

DOE, 1990. Tiger Team Report for SSFL. U.S. Department of Energy, Washington, DC.

DOE, 1992. Federal Facility Agreement for the Oak Ridge Reservation. U.S. Department of Energy, DOE/OR-1014.

DOE, 1993. Final Report on the Background Soil Characterization Project at the Oak Ridge Reservation, Oak Ridge, Tennessee, Volumes 1–3, DOE/OR/01-1175/V1-3.

DOE, 1996. Methods for Conducting Human Health Risk Assessments and Risk Evaluations at Paducah Gaseous Diffusion Plant, DOE/OR/07-1506&D1, Lockheed Martin Energy Systems, Oak Ridge National Laboratory, Oak Ridge, Tennessee.

DOE, 1997. Assessment of Short-term and Long-term Risks for Remedy Selection, DOE/EH-413-9708, Office of Environmental Policy and Assistance, Washington, D.C.

DOE, 1998a. Federal Facility Agreement for the Paducah Gaseous Diffusion Plant, DOE/OR.

DOE, 1998b. U. S. Department of Energy Environmental Management Program, Initial Accelerating Cleanup Paths to Closure Oak Ridge Operations Office, DOE/OR/01-1746, Bechtel Jacobs Company, LLC, Oak Ridge, Tennessee.

DOE, 2004. U.S. Dept of Energy Schedules Public Meeting June 3 to Discuss Groundwater Sampling at Energy Technology Engineering Center. May 19, 2004.

DOE and EPA, 1995. Policy on Decommissioning of Department of Energy Facilities Under the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA), Lockheed Martin Energy Systems, Inc., Oak Ridge, Tennessee.

DOE, various years. Quarterly Emission Report, Energy Technology Engineering Center, Sodium Components Test Installation, H1 and H2 Sodium Heaters #001136, 1984-1996.

DTSC, 2003. Perchlorate Update: DTSC and RWQCB Sample Locations, Simi Valley, and SSFL, Preliminary Draft, September, 2003.

DWP, 2004. Final Site Investigation Report on Soil Suitability Evaluation at Chatsworth Reservoir, Los Angeles Department of Water and Power.

Ecology and Environment, 1989. Summary Review of Preliminary Assessments/Site Inspections of Rockwell International SSFL. TTD #F9-8907-015. Ecology and Environment Inc., San Francisco, CA.

Ecology and Environment, 1991. Environmental Priorities Initiative Preliminary Assessment for Hughes Aircraft Company. TTD #F9-9105-010. Ecology and Environment Inc., San Francisco, CA.

EG&G, 1979. Aerial Radiological Surveys of Rockwell International Facilities. Prepared for the U.S. Nuclear Regulatory Commission by the Remote Sensing Laboratory of the U.S. DOE (Contract Report EGG-1183-1751), Las Vegas, NV, October 1979.

EMCON, 1999. Groundwater Remediations Operations Plans for Rocketdyne International, SSFL, May 25, 1990, Revision 4 April 29, 1999.

EPA, 1984a. Health and Environmental Effects Profile for Hydrazine and Hydrazine Sulfate. U.S. Environmental Protection Agency, Office of Health and Environmental Assessment, Environmental Criteria and Assessment Office, Washington DC: Office of Solid Waste and Emergency Response.

EPA, 1984b. Health and Environmental Effects Profile for 1,1-Dimethylhydrazine. EPA/600/x-84/134. U.S. Environmental Protection Agency, Office of Research and Development, Office of Health and Environmental Assessment, Environmental Criteria and Assessment Office, Cincinnati, OH.

EPA, 1986. Guidelines for Groundwater Classification under the EPA Groundwater Protection Strategy. U.S. Environmental Protection Agency, Office of Research and Development, Washington, DC.

EPA, 1988. Guidance for Conducting Remedial Investigations and Feasibility Studies Under CERCLA. EPA/540/G- 89/004. U.S. Environmental Protection Agency, Office of Emergency and Remedial Response, Washington, DC.

EPA, 1989a. Unpublished letter re: site visit to SSFL, from US EPA, Office of Radiation Programs (Gregg Dempsey), to SSFL, Emergency Response Unit (Daniel Shane, on scene coordinator), July 28, 1989.

EPA, 1989b. Superfund Groundwater Issue: Groundwater Sampling for Metal Analyses. U.S. Environmental Protection Agency, Office of Solid Waste and Emergency Response, Office of Emergency and Remedial Response, Washington DC.

EPA, 1989c. Risk Assessment Guidance for Superfund: Volume 1-Human Health Evaluation Manual (Part A). EPA/540/1-89/002. U.S. Environmental Protection Agency, Office of Emergency and Remedial Response, Washington, DC.

EPA, 1989d. Risk Assessment Guidance for Superfund, Interim Final. EPA/540/1-89-002. U.S. Environmental Protection Agency, Office of Emergency and Remedial Response, Washington, DC.

EPA, 1990. Guidance for Data Usability in Risk Assessment. EPA/540/G-90/008. U.S. Environmental Protection Agency, Office of Emergency and Remedial Response, Washington, DC.

EPA, 1991a. Risk Assessment Guidance for Superfund. Volume I, Human Health Evaluation Manual (Part B, Development of Risk-Based Preliminary Remediation Goals), OSWER Directive 9285.7-01B. U.S. Environmental Protection Agency, Office of Emergency and Remedial Response, Washington, DC.

EPA, 1991b. Risk Assessment Guidance for Superfund. Volume I, Human Health Evaluation Manual (Part C, Risk Evaluation of Remedial Alternatives), OSWER Directive 9285.7-01C. U.S. Environmental Protection Agency, Office of Emergency and Remedial Response, Washington, DC.

EPA, 1991c. Standard Default Factors, OSWER Directive 9285.6-03. U.S. Environmental Protection Agency, Office of Emergency and Remedial Response, Washington, DC.

EPA, 1991d. Appendix D of RAGS, Vol. 1, Human Health (“Corrections to RAGS—Part B, Sections 3.3.1 and 3.3.2”).

EPA, 1992. Dermal Exposure Assessment: Principles and Application, Interim Report. EPA/600/8-91/011B. U.S. Environmental Protection Agency, Office of Research and Development, Washington, DC.

EPA, 1993. Guidance on Conducting Non-Time Critical Removal Actions Under CERCLA. EPA/540-R-93-057. U.S. Environmental Protection Agency, Office of Emergency and Remedial Response, Washington, DC.

EPA, 1994. Health Effects Assessment Summary Tables. Prepared by the Office of Health and Environmental Assessment. U.S. Environmental Protection Agency, Environmental Assessment and Criteria Office, Cincinnati, Ohio, for the Office of Solid Waste and Emergency Response, Office of Emergency and Remedial Response, Washington DC.

EPA, 1995a. Integrated Risk Information System (IRIS). U.S. Environmental Protection Agency, Health Criteria and Assessment Office, Cincinnati, OH.

EPA, 1995b. Exposure Factors Handbook. EPA/600/8-89/043. U.S. Environmental Protection Agency, Office of Health and Environmental Assessment, Washington, DC.

EPA, 1995c. User’s Guide for the Industrial Source Complex (ISC3) Dispersion Models, Volumes 1, 2, and 3. EPA-454/B-95-003 A, B, and C. Pacific Environmental Services, Inc., and U.S. EPA, Research Triangle Park, NC, September 1995.

EPA, 1996a. Supplemental Guidance to RAGS: Region 4 Bulletins, Human Health Risk Assessment (Interim Guidance), Waste Management Division, Office of Technical Services.

EPA, 1996b. Soil Screening Guidance: User’s Guide. EPA/540/R-96/018. U.S. Environmental Protection Agency, Office of Emergency and Remedial Response, Washington, DC.

EPA, 1997. Emission Inventory Improvement Program, Volume III: Area Sources, Chapter 6: Solvent Cleaning. <http://www.epa.gov/ttn/chiep/eiip/techreport/volume03/index.html>.

EPA, 1998a. Compilation of Air Pollutant Emission Factors, AP-42. Section 1.3: Fuel Oil Combustion. Volume 1, 5th ed., September. <http://www.epa.gov/ttn/chiep/ap42/ch01/>.

EPA, 1998b. Risk Assessment Guidance for Superfund, Volume I: Human Health Evaluation Manual (Part D, Standardized Planning, Reporting, and Review of Superfund Risk Assessments) Interim. Publication 9285.7-01D. U.S. Environmental Protection Agency, Office of Emergency and Remedial Response, Washington, DC.

EPA, 1998c. Perchlorate Environmental Contamination: Toxicological Review and Risk Characterization Based on Emerging Information. Review Draft. NCEA-1-0503. U.S. Environmental Protection Agency, Office of Research and Development, Washington, DC.

EPA, 1999. Perchlorate. U.S. Environmental Protection Agency, Office of Ground Water and Drinking Water.

EPA, 2000. Analysis of Samples Collected by CA-DGS Env. Measurement Branch. Letter from EPA Office of Radiation Programs, Las Vegas, NV, Jan 12, 1990, to DHS, Bill Watson.

EPA, 2001a. Sources, Emission and Exposure for Trichloroethylene (TCE) and Related Chemicals. EPA/600/R-00-099. U.S. Environmental Protection Agency, Office of Research and Development, National Center for Environmental Assessment, Washington, DC.
<http://www.epa.gov/nceawww1/pdfs/tce/TCEMarch2001.pdf>.

EPA, 2001b. Appendix W to Part 51—Guideline on Air Quality Models. 40 CFR Ch. I(7-1-01 Edition), p. 387.

EPA, 2002. Guidance on Choosing a Sampling Design for Environmental Data Collection for Use in Developing a Quality Assurance Project Plan. EPA QA/G-5S, 2002.

EPA, 2003a. Hazard Ranking System (HRS) of the Santa Susana Field Laboratory Area IV Energy Technology and Engineering Center (ETEC).

EPA, 2003b. EPA's Comments on the Department of Energy's (DOE) Final Environmental Assessment (EA) and Finding of No Significant Impact (FONSI) at ETEC. Unpublished letter, December 5, 2003.

EPA, 2003c. AERMOD: Latest Features and Evaluation Results. EPA-454/R-03-003. U.S. Environmental Protection Agency, Office of Air Quality Planning and Standards. June.

ERC, 1990a. Santa Susana Field Laboratory Assessment Phase: Initial Laboratory Assessment Phase I: Initial Evaluation Study. ERC Environmental and Energy Services.

ERC, 1990b. Final Report: SSFL Exposure Assessment Phase I: Initial Study for Impact Assessment. ERC Environment and Energy Services.

ERD, 1992. Use of Three-Dimensional High Resolution Seismic Technology to Optimize the Location of Remedial Systems. UCRL-AR-111786. Environmental Restoration Division, Resolution Resources.

ERG, 2001. SSFL-related documents from Matthew N. Mitchell of ERG to Courtney Gorin of STI. December 13.

Erickson, M.D., ed., 1986. Analytical Chemistry of PCBs. Stoneham, MA: Butterworth Publishers.

ETEC, 1987. Rockwell Int. Corp., Energy Technical Engineering Center, CERCLA Phase II Site Characterization, May 29, 1987.

Federal Register, Hazard Ranking System: Final Rule. Fed. Regist. 55(241): 51532-51667, 1990.

Fine, D.H., and D.P. Rounbehler, 1981. Occurrence of N-Nitrosoamines in the Workplace: Some Recent Developments. In: Scanlan, R.A., and S.R. Tannenbaum, eds. N-Nitroso Compound. ACS Symposium, Series No 174. Washington, DC: American Chemical Society. pp. 207-216.

Finlayson-Pitts, B., and J. Pitts, 2000. Chemistry of the Upper and Lower Atmosphere—Theory, Experiments and Applications. Academic Press, San Diego, CA.

Freeze, R.A., and J.A. Cherry, 1979. Groundwater. Prentice Hall, Inc. Englewood Cliffs, NJ.

Froines, J., 1999. Appendix A: Use and Toxicology of Chemicals at Rocket-Engine Test Stands. Epidemiological Study to Determine Possible Adverse Effects to Rocketdyne/Atomics International Workers from Exposure to Selected Chemicals. January.

Garbarini and Lion, 1986. Influence of the Nature of Soil Organics on the Sorption of Toluene and Trichloroethylene. Environ. Sci. Technol. 20: 1263-1269.

GEMS, 1990. Graphical Exposure Modeling System. U.S. Environmental Protection Agency, Office of Pesticides and Toxic Substances.

GRC, 1986. Phase II Groundwater Inv., SSFL, Area II, Rockwell Int., Rocketdyne Div. Groundwater Resource Consultants, Tucson, AZ, October 29, 1986.

GRC, 1987. Hydrogeologic Assessment Report, SSFL, Rockwell International, Rocketdyne Div. Groundwater Resource Consultants, Tucson, AZ, November 30, 1987.

GRC, 1988a. Preliminary Assessment Report, SSFL Lab, Area II, Rockwell International, Rocketdyne Division. Groundwater Resource Consultants, Tucson, AZ, March 3, 1988.

GRC, 1988b. Hazardous Ranking System Report, Santa Susana Field Laboratory, Area II, Rockwell International Corporation, Rocketdyne Division, Ventura County, California. Groundwater Resource Consultants, Tucson, AZ, March 3, 1988.

GRC, 1990a. Hydrologic Assessment Report, Lower Pond Building 886 Sodium Disposal Facility, SSFL. Groundwater Resources Consultants, Tucson, AZ, June 12, 1990.

GRC, 1990b. Area IV Radiological Investigation Report, SSFL, Rockwell Int. Corp., Rocketdyne Division. Groundwater Resources Consultants, Tucson, AZ, March 23, 1990.

GRC, 1990c. Investigation of Naturally Occurring Radionuclides in Rock, Soils, and Groundwater, SSFL, Ventura Co. Groundwater Resources Consultants, Tucson, AZ, June 1, 1990.

GRC, 1993. Soil Sampling, Area I: Thermal Treatment Unit. 8640M-206 Prepared for Rockwell International Corporation, Rocketdyne Division, by Groundwater Resource Consultants, Tucson AZ, August 16, 1993.

GRC, 1994. Facility Location Map (Figure 1). Prepared for Rockwell Intern. Corp. 1994 Annual Groundwater Monitoring Report. 8640M-246. Groundwater Resource Consultants, Tucson, AZ, 1994.

GRC, 1995. Well Compendium. 8640M-89C. Prepared for Rockwell International Corporation, Rocketdyne Division, by Groundwater Resource Consultants, Tucson, AZ, September 20, 1995.

GRC, 1998. Off-Site Well Inventory. 8640M-361. Prepared for Santa Susana Field Laboratory, Boeing North American, Inc., Rocketdyne Propulsion and Power, by Groundwater Resource Consultants, Tucson, AZ, July 9, 1998.

GRC, 1999. Annual Groundwater Monitoring Report, Santa Susana Field Laboratory, 1998. 5 Volumes Plus Appendices. Prepared for Boeing North American, Inc., Ventura County, CA, by Groundwater Resource Consultants, Tucson AZ, February 24, 1999.

GRC, 2000. Annual Groundwater Monitoring Report (1999). Groundwater Resource Consultants, Tucson, AZ, February 28, 2000.

Grifoll, J., and Y. Cohen, 1994. Chemical Volatilization from the Soil Matrix: Transport through the Air and Water Phases. *J. Hazard. Mater.* 37: 445-457.

Haley-Aldrich, 2000. Annual Groundwater Monitoring, SSFL, Ventura, CA, Call #R-SV00628.

Hansen, J., et al., 2001. Cancer Incidence Among Danish Workers Exposed to Trichloroethylene. *J Occup Environ Med.* 43(2):133-139.

Harbison, R.D., 1986. Genotoxic Effects of PCBs. Monsanto Chem., St. Louis, MO.

Hargis and Associates, 1985. Phase I Investigation of the Hydrogeologic Conditions at SSFL, Ventura Co., CA, 1985.

Harmon, T.C. and P.V. Roberts, 1994. Comparison of intraparticle sorption and desorption rates for a halogenated alkene in a sandy aquifer material, *Environ. Sci. Technol.* 28: 1650-1660 (1994).

Hart, R.S., 1962. Distribution of Fission Product Contamination in the SRE. AEC Research and Development Report, NAA-SR-6890 (Contract AT(11-1)-GEN-8), Atomics International, Canoga Park, CA, March 1, 1962.

Hayduk, W., and H. Laudie, 1974. Prediction of Diffusion Coefficient for Non-Electrolytes in Dilute Aqueous Solutions. *AIChE J.* 20: 611-615.

Henschler, D., M. Vamvakas, W. Lammert, B. Dekant, B. Thomas, and K. Ulm, 1995. Increased Incidence of Renal Cell Tumors in a Cohort Study of Cardboard Workers Exposed to Trichloroethene. *Arch. Toxicol.* 69: 291-299.

Hughes, 1989. Potential Source Area Investigation Report for the Hughes Missile Systems Group, Canoga Park, CA. Hughes Safety, Health and Environmental Affairs, Hughes Missile Systems Group, Canoga Park, CA, and McLaren/Hart Environmental Engineering Corp., Irvine, CA, November 30, 1989.

Hunter, P., B. Davis, and F. Roach, 2005. Naturally occurring concentrations of inorganic chemicals in groundwater and soil at California air force bases. 44th Annual Meeting of the Soc. of Toxicology. New Orleans, LA, March 10, 2005.

Hurley, J.C., B.L. Parker, and J.A. Cherry, 2003. Source Zone Characterization at the Santa Susana Field Laboratory: Rock Core VOC Results for Core Holes C1 through C7. University of Waterloo, Department of Earth Sciences, December 22, 2003.

IARC, 1974. IARC Monographs on the Evaluation of the Carcinogenic Risk of Chemicals to Man: Some Aromatic Amines, Hydrazines and Related Substances, N-Nitroso Compounds and Miscellaneous

Alkylating Agents. Vol 4. World Health Organization, International Agency for Research on Cancer, Lyon, France.

IARC, 1991. IARC Monographs on the Evaluation of the Carcinogenic Risks to Humans, Vol. 52, Chlorinated Drinking Water; Chlorination By-Products; Some Other Halogenated Compounds; Cobalt and Cobalt Compounds. International Agency for Research on Cancer, Lyon, France. pp. 179-268.

ICF Kaiser, 1993. Current Conditions Report and Draft RCRA Facility Investigation Work Plan, incl. Appendix F, Reported Releases at Rocketdyne SSFL, 1975-1990. Santa Susana Field Laboratory, 1993.

ICF Kaiser, 1995. Former Sodium Disposal Facility Santa Susana Field Laboratory Closure Report. Document No. SSFL-95-03. October 1995.

ITC, 1999. Draft Final Interim Measures Risk Assessment, Former Sodium Disposal Facility. IT Corporation, Pasadena, CA, July 9, 1999.

Jin, Y., and W.A. Jury, 1996. Characterizing the Dependence of Gas Diffusion Coefficient on Soil Properties. *Soil Sci. Soc. Am. J.* 60: 66-71.

Klinefelder, 2000. Report of Env. Sampling, Ahmanson Ranch Project, County of Ventura, CA. #58-9168-01-0001. Prepared for Ahmanson Land Co. by Klinefelder, Diamond Bar, CA, 91765-3910, January 27, 2000.

Kurtio, P., E. Pukkala, H. Kahelin, A. Auvinen, and J. Pekkanen, 1999. Arsenic Concentrations in Well Water and Risk of Bladder and Kidney Cancer in Finland. *Environ. Health Perspect.* 107: 705-710.

Lafflam, S.R., 1989. Letter from Mr. S.R. Lafflam, Rockwell International, to Mr. D. Dickerson, California Department of Health Services, Toxic Substance Control Division, re: Solid Waste Management Unit (SWMU) Submittal for Rockwell International Corporation, Rocketdyne Division, Santa Susana Field Laboratory, Including Information Regarding Potential Releases from Solid Waste Management Units, Rockwell International, Canoga Park, CA, September 14, 1989.

Lafflam, S., 1993 and 2004. Personal communication during site visit (6/1/1993) and communication during DOE meeting (6/3/2004).

Lawrence Livermore National Laboratory, 1997. An Investigation on the Cs-137 Content of Soil Collected from Boeing North American Inc., Employees' Recreational and Fitness Center in Canoga Park (CA). June 20, 1997.

Loper, G.L., 1977. Gas Phase Kinetic Study of Air Oxidation of UDMH. In: *Proceedings of the Conference on the Environmental Chemistry of Hydrazines Fuels*, CEEDO-TR-78-14. 1977: 129-159.

Lunn, G., and E.B. Sansone, 1994. Oxidation of 1,1-Dimethylhydrazine (UDMH) in Aqueous Solution with Air and Hydrogen Peroxide. *Chemosphere* 29: 1577-1590.

Masry and Vititoe, 1998. Letter dated Nov 23, 1998, from Masry and Vititoe Law Offices to Susan Lacey re: Ahmanson Ranch (PM913 and Subdiv. Exemption 98-02), results by Analytical Chemists.

McKone, T.E., 1987. Human Exposure to Volatile Organic Compounds in Household Tap Water: the Indoor Inhalation Pathway. *Environ. Sci. Technol.* 21: 1194-1201.

McLaren/Hart, 1990. Phase One Remedial Investigation at the Hughes Missile Systems Group Facility, Dec 20, 1990.

McLaren/Hart, 1993. Multimedia Sampling Report for the Brandeis-Bardin Institute and the Santa Monica Mountains Conservancy. 6 Vols. McLaren/Hart Environmental Engineering Corp., Irvine, CA, March 10, 1993.

McLaren/Hart, 1995. Additional Soil and Water Sampling at the Brandeis-Bardin Institute and the Santa Monica Mountains Conservancy. 6 Vols. McLaren/Hart Environmental Engineering Corp., Irvine, CA, January 1995.

Melvold, R.W., 1992. Unpublished letter from R.W. Melvold, Manager, Air Quality Programs, Rocketdyne Division, to Ventura County Air Pollution Control District, re: AB2588 ATIR, Revision B for SSFL Areas I, II, and III. Rockwell International, Rocketdyne Division, Canoga Park, CA, October 13, 1992.

Melvold, R., 1994. AB 2588 1992 Biennial Update Report, SSFL Areas I, II, and III. Rocketdyne Division.

Montgomery Watson. 2000a. Technical Memorandum, Conceptual Site Model, Movement of TCE in the Chatsworth Formation, Santa Susana Field Laboratory, Volumes I, II and III, April 2000.

Montgomery Watson, 2000b. Workplan for Additional Field Investigations, Chatsworth Formation Operable Unit, October 2000.

Montgomery Watson, 2002. Technical Memorandum, Geologic Characterization of Eastern Portion of the Santa Susana Field Laboratory. Prepared for Boeing by MWH, Walnut Creek, CA, February, 2002.

Montgomery Watson Harza (MWH), 2003a. Perchlorate Source Evaluation and Technical Report, Santa Susana Field Laboratory, Ventura County, CA, February, 2003.

Montgomery Watson Harza, 2003b. Perchlorate Source Evaluation and Technical Report Update Volumes I and II, Santa Susana Field Laboratory, Ventura County, CA, January through September, 2003.

Montgomery Watson Harza, 2003c. Northern Drainage Perchlorate Sampling Results Technical Memorandum, Santa Susana Field Laboratory, Ventura County, CA, November, 2003.

Montgomery Watson Harza, 2004. Report of Results: Phase I Northeast Investigation Area Groundwater Characterization, Santa Susana Field Laboratory, Ventura County, CA, September, 2004.

Morgan, R.W., M.A. Kelsh, K. Zhao, S. and Heringer, 1998. Mortality of aerospace workers exposed to trichloroethylene. *Epidemiology* 9: 424-431.

Morgenstern, H., et al., 1997. Epidemiologic Study to Determine Possible Adverse Effects to Rocketdyne/Atomics International Workers from Exposure to Ionizing Radiation. Final Report to the Public Health Institute, Berkeley, CA (Subcontract No. 324A-8701-S0163), June 1997.

Morgenstern, H., et al., 1999. Epidemiologic Study to Determine Possible Adverse Effects to Rocketdyne/Atomics International Workers from Exposure to Selected Chemicals. Addendum Report to the Public Health Institute, Berkeley, CA (Subcontract No. 324A-8701-S0163), January 1999.

Morgenstern, H., and B. Ritz, 2001. Effects of Radiation and Chemical Exposures on Cancer Mortality Among Rocketdyne Workers: A Review of Three Cohort Studies. *Occupational Medicine: State of the Art Reviews* 16(2): 219-238.

MWG, 2003. Perchlorate Source Evaluation and Technical Report, Santa Susana Field Laboratory, Ventura County, California. Prepared for Rocketdyne by MWG, Pasadena, CA, February 2003.

National Research Council, Ranking Hazardous-Waste Sites for Remedial Action. National Academy Press, Washington, DC, 1994.

North American Aviation, Inc., 1960. Procedures for Pentaborane (PB) Activities Propulsion Research Area (PRA). Propulsion Field Laboratory. Rockwell International, Rocketdyne Divisions, Canoga Park, CA.

Oak Ridge Associated Universities, 1986. Confirmatory Radiological Survey of the L-85 Reactor Facility, Rocketdyne Division, Rockwell International Corporation, Santa Susana, California. December.

Oak Ridge Institute, 1997. Verification Survey of the Interim Storage Facility (T654) Santa Susana Field Laboratory, Rockwell International Corporation, Ventura County, California. Oak Ridge Institute of Science and Education, November 1997.

OEHHA, 1994. California Cancer Potency Factors. Memo from David Siegel to the Standards and Criteria Workgroup. California Environmental Protection Agency, Office of Environmental Health Hazard Assessment, Sacramento, CA.

Oldenkamp, R.D., and J.C. Mills, 1991. Nuclear Operations at Rockwell's Santa Susana Field Laboratory—A Factual Perspective. Rockwell International Document N001ER000017, Rev. C. Canoga Park, CA, September 1991.

Ogden, Inc., 1995. Soil Radiation Levels, East Ventura, West 2A Counties. Database, 1992-1995.

Ogden Inc., 1998a. Bell Canyon Area Soil Sampling Report, Ventura County, California. Ogden Environmental and Energy Services Co., Inc. San Diego, CA, October 1998.

Ogden Inc., 1998b. SSFL RCRA Facility Investigation Background Data in the Standardized Risk Assessment Methodology, Ogden Environmental and Energy Services Co., Inc. San Diego, CA, 1998.

Ogden, Inc., 1999. Rocketdyne Santa Susana Field Laboratory Solid Waste Management Unit Map and Analytical Data. Ogden Environmental and Energy Services Co., Inc. San Diego, CA, September 1999.

Paillet, F.L., and K. Kapucu, 1989. Fracture Characterization and Fracture Permeability Estimates from Geophysical Logs in the Mirror Lake Watershed, New Hampshire: U.S. Geological Survey Water-Resources Investigations Report 89-4058.

PEC, 1999. Windrose Data from SSFL Meteorological Station. Precise Environmental Consultants, 1960 to present.

Podoll, R.T., Jaber, H.M., and R.E. Bisque, 1970. Natural Organic Acids as Agents of Chemical Weathering. U.S. Geological Survey Professional Paper 700-C:130-137.

Pohl, H., N. Roney, S. Wilbur, H. Hansen, C. DeRosa, 2003. Six Interaction Profiles for Simple Mixtures. *Chemosphere* 53: 183-197.

Police and Fireman's Benefit Society Report, December 13, 1961.

PSOMAS, 2003. Ahmanson Ranch Hydrogeological Monitoring Sept 2002-Nov. 2002: Quarterly Report to Regional Water Quality County Board.

Reynolds, P., et al., 1992. Cancer Incidence near the Santa Susana Field Laboratory, 1978-1989. California Department of Health Services, 1992.

Robinson, K.S., ed., 1998. Rocketdyne Propulsion and Power DOE Operations Annual Site Environmental Report, 1997. Prepared for U.S. Department of Energy, Oakland Operations Office, by Rocketdyne Propulsion and Power, November 23, 1998.

Rocketdyne, 1958-1960. Unpublished. Monthly Chemical Disposal Activity Reports, 1958 to 1960, Rocketdyne inter-office Letters, Santa Susana, CA.

Rocketdyne, 1959-1989. Unpublished. Annual Site Environmental Reports, 1959 to 1989, Rocketdyne, Santa Susana, CA.

Rocketdyne, 1959-1960. Inter-office letters. Monthly Report. Chemical Disposal—Activities at Pits, Inspections, Burning, Convoying, Etc.

Rocketdyne, 1988. Groundwater Remedial Action Plan, Santa Susana Field Laboratory, Rockwell International Corporation, Rocketdyne Division, Ventura County, California. #8640M.33. April 14, 1988.

Rocketdyne, 1991. Tritium Production and Release to Groundwater at SSFL, Supporting Documentation NOOISRR-140120, Dec 6, 1991.

Rocketdyne, 1992. AB 2588 ATIR, Revisions B for SSFL Areas I, II and III. Correspondence from R.W. Melvold to Ventura County Air Pollution Control District. October 13.

Rocketdyne, 1994a. AB 2588 1992 Biennial Update Report, SSFL Areas I, II and III. Correspondence from R.W. Melvold to Ventura County Air Pollution Control District. July 22.

Rocketdyne, 1994b. 1992 Biennial Update—AB2588 1992 Biennial Update Report, SSFL Area IV. Correspondence from Kim O'Rourke for R.W. Melvold to Ventura County Air Pollution Control District. June 8.

Rocketdyne, 1994c. 1992 Biennial Update—Air Toxics Emission Inventory Report (ATEIR) SSFL Area IV. Correspondence from R.W. Melvold to Ventura County Air Pollution Control District. February 24.

Rocketdyne, 1995. Division Annual Site Environmental Report—SSFL and DeSoto Sites—1994. September 30, 1995.

Rocketdyne, 1996. Area IV Radiological Characterization Survey, Final Report. 5 Vols. A4CM-ZR-0011. Rockwell International, Rocketdyne Division, Canoga Park, CA.

Rocketdyne, 1997. Air Toxics "Hot Spots" Update Summary Form for SSFL Area IV (Permit #0271). Correspondence from Kim O'Rourke to Ventura County Air Pollution Control District. July 31.

Rocketdyne, 1998. 1997 AB2588 Air Toxic Emission Inventory Report for SSFL Permit to Operate #0271. Correspondence from Kim O'Rourke to Ventura County Air Pollution Control District. November 30.

Rocketdyne, 1999a. Personnel communication with Michael Sullivan, Rocketdyne, re: Surface Drainage at SSFL, October, 1999.

Rocketdyne, 1999b. Overview of Rocket Engine Testing and Rocket Engine Fuels and Oxidizers Used at SSFL. Various dates (1955 to present). Received November, 1999.

Rocketdyne, 1999c. 1997 AB2588 Air Toxic Emission Inventory Report for SSFL Permit to Operate #0271—Additional Information. Correspondence from Kim O'Rourke to Ventura County Air Pollution Control District. February 1.

Rocketdyne, 1999d. 1997 AB2588 Air Toxic Emission Inventory Report for SSFL Permit to Operate #0271—Response to Questions. Correspondence from Kim O'Rourke to Ventura County Air Pollution Control District. March 9.

Rocketdyne, 2003. AB2588 Air Toxic "Hot Spots" Program Emission Inventory Report for 2002. Santa Susana Field Laboratory Areas I, II, II, Facility 00232. Correspondence from Paul Costa, Manager, to Ventura County Air Pollution Control District. September 4.

Rockwell International, 1981. Analysis of Rocket Engine Exhaust at STL-4, Santa Susana.

Rockwell International, 1982. Letter (Ref. # 82RC03913) from J.A. Bowman, Mgr., Facilities Engineering, to Mr. Richard Carlson, Ventura County Air Pollution Control District, including detailed emission calculations. Rocketdyne Division, Canoga Park, CA, April 15, 1982.

Rockwell International, 1984. Estimation of Pollutants in Rocket Exhaust. EMSC8035.7FR(2). Final report revised May 22.

Rockwell International, 1987. Energy Technology Engineering Center, CERCLA Program Phase II—Site Characterization, May 29, 1987.

Rockwell International, 1992a. Area I Thermal Treatment Facility. Revised Closure Plan. CAD 093 365 435. Rockwell International, Rocketdyne Division, Canoga Park CA, January 2.

Rockwell International, 1992b. Rocketdyne letter 92RC06401 from R.W. Melvold, Manager, Air Quality Programs, to Terri Thomas, Ventura County Air Pollution Control District. Toxic Release Inventory. October 13.

Rockwell International, 1994. Rocketdyne letter 94RC05634 to Henry Chin, Ventura County Air Pollution Control District. Toxic Release Inventory. July 22.

Rockwell International, 1999. Solid Rocket Engine Exhaust Containment System. October 25.

Rutherford, P.D., 1994a. Unpublished letters from P. Rutherford re: (1) soil sample results for 10020 Shoup Ave., Chatsworth, to J. Wang. June 8, 1994; (2) soil sample results for 501 Southby Ave., West Hills, to R. Franklin. July 8, 1994.

Rutherford, P.D., ed., 1999. Site Environmental Report for Calendar Year 1998, DOE Operations at Rocketdyne Propulsion and Power RD99-115. Final Draft, Rockwell International, Rocketdyne Division, Canoga Park CA, July 1999.

RWQCB, 1991. Unpublished letter from RWQCB (M. Chakrabarti and J.E. Ross) to Rockwell Int. (S. Lafflam) re: GRC, 1990. Los Angeles Regional Water Quality Control Board, March 1991.

RWQCB, 2003. Memorandum, Update on Perchlorate Groundwater Pollution Within the Los Angeles Region. Los Angeles Regional Water Quality Control Board, April 28, 2003.

SAIC, 1994. Final RCRA Facility Assessment Report for Rockwell International Corporation, Rocketdyne Division, Santa Susana Field Laboratory, Ventura County, California. EPA Contract No. 68-W9-0008. Prepared for U.S. Environmental Protection Agency, Region IX, by Science Applications International Corporation.

Schwarzenbach, R.P., P.M. Gschwend, and D.M. Imboden, 1993. Environmental Organic Chemistry. John Wiley & Sons, NY.

Scire J.S., D.G. Strimaitis, and R.J. Yamartino, 1995. User's Guide for the CALPUFF Dispersion Model. No. 1406-02. Prepared for U.S. Department of Agriculture, Forest Service, Cadillac, MI, by EARTH TECH/Sigma Research Corp., Concord, MA.

SCWC, 2002-2004. Southern California Water Quality Report for Simi Valley.

Spirtas, R., P.A. Stewart, J.S. Lee, et al., 1991. Retrospective Cohort Mortality Study of Workers at an Aircraft Maintenance Facility. *Br. J. Ind. Med.* 48: 515-530.

Stone, D.A., 1980. The Vapor Phase Oxidation of Unsymmetrical Dimethylhydrazine and 50-Percent Unsymmetrical Dimethylhydrazine-50-Percent Hydrazine Mixtures, NTIS AD-A090281: ESL-TR-80-21. *Chem. Abs.* 95: 61037a.

Suder, D., 1999. Historical Wind Data from Santa Susanna Field Laboratory. Memorandum prepared for Boeing-Rocketdyne by Precise Environmental Consultants, Davis, CA, November 15.

Sudicky, E.A., and R.G. McLaren, 1992. The Laplace Transform Galerkin Technique for Large-Scale Simulation of Mass Transport in Discretely Fractured Porous Formations. *Water Resources Research* 28(2): 499-514.

Sullivan, M., 1999. Information on Rocket Engine Tests. Facsimile. SSFL. October 25. To Brend Weiss.

Susarla, S., T.W. Collette, A.W. Garrison, N.L. Wolfe, and S.C. McCutcheon, 1999. Perchlorate Identification in Fertilizers. *Env. Sci. Tech.* 33(5): 110A-111A.

Tabidian, A., 2003. Personal communication. Department of Geological Engineering, California State University, Northridge, CA. October 2003.

Tchounwou, P.B., J.A. Centeno, and A.K. Patolla, 2004. Arsenic toxicity, mutagenesis, and carcinogenesis—a health risk assessment and mutagenesis approach. *Mol. Cell Biochem.* 255(1-2): 47-55.

Techlaw, 1990. Baseline Public Health and Environmental Risk Assessment for Santa Susana Field Laboratory, Rockwell International Corporation, Rocketdyne Division, Ventura, California, October, 1990.

Tri-Counties Regional Cancer Registry, 1997. Unpublished letter report from the Tri-Counties Regional Cancer Registry to Director, Ventura County Public Health.

Tuttle, R.J., 1992. Tritium Production and Release to Groundwater at SSFL. Rockwell International Safety Review Report No. N001SRR140120. Rockwell International Corporation, Canoga Park, CA, December 1992.

Urry, W.H., A.L. Olsen, H.W. Kruse, E.M. Bens, C. Ikoku, and Z. Gaibel, 1965. Autooxidation of 1,1-Dimethylhydrazine, NTIS AD-622785: NAVWEPS Report 8798. Chem. Abs. 64: 14078e.

USGS, 1952. Calabaras Quadrangle, California. 7.5 Minute Series (Topographic) Map. U.S. Department of the Interior, Geological Survey, Denver, CO.

USGS, 1967. Calabaras Quadrangle, California. 7.5 Minute Series (Topographic) Map. U.S. Department of the Interior, Geological Survey, Denver, CO.

Van Rooij, J.G.M., M.M. Bodelier-Bade, and F.J. Jongeneelen, 1993a. Estimation of Individual Dermal and Respiratory Uptake of Polycyclic Aromatic Hydrocarbons in 12 Coke Oven Workers. Brit. J. Ind. Med. 50: 623-632.

Van Rooij, J.G.M., M.M. Bodelier-Bade, and F.J. Jongeneelen, 1993b. Absorption of Polycyclic Aromatic Hydrocarbons Through Human Skin: Differences Between Anatomical Sites and Individuals. J. Toxicol. Environ. Health 38: 355-368.

VCAPCD, 1989. Summary Review of Preliminary Assessment/Site Inspection of Santa Susana Field Laboratory. Ecology and Environment, Ventura County Air Pollution Control District, Permit Department, CA, July 19, 1989.

Watermaster, 1987. Upper Los Angeles River Area Watermaster, Watermaster Service in the Upper Los Angeles River Area, Los Angeles County, Oct. 1, 1986-Sept. 30, 1987, May 1987.

Weis, N.S., 1996. Cancer in Relation to Occupational Comparisons Do Not Always Control for the Healthy Worker Effect (Abstract). Am. J. Epidemiol. 141(Suppl): S58.

WHO, 1976. Accumulation of Toxic Metals with Special Reference to Their Adsorption, Excretion, and Biological Halftimes. Environ. Phys. Biochem. 3: 65-67.

WHO, 1987a. Environmental Health Criteria 68: Hydrazine. Published under the joint sponsorship of the United Nations Environmental Programme, the International Labour Organisation, and the World Health Organization.

WHO, 1987b. Updating of IARC Monographs. Vol 1-42, Suppl 7. Lyon, France: IARC, 1987b.

Wright, W.E., and C. Perkins, 1990. Cancer Incidence in Five Los Angeles County Census Tracts. Research and Surveillance Section, 1990.